

# Flooded Vehicle Resources

- Electrical Repair Guidelines for Vehicles Subjected to Flooding Conditions- SFN 06-27
  - [https://evaluate.internationaldelivers.com/service/sfns/sfn0627\\_1.xml](https://evaluate.internationaldelivers.com/service/sfns/sfn0627_1.xml)
- Inspection and Correction Procedures for International® Engines Subjected to Flood Water- TSI 05-12-36
  - [https://evaluate.internationaldelivers.com/service/tsis/051236\\_1.xml](https://evaluate.internationaldelivers.com/service/tsis/051236_1.xml)
- Cummins Inc. Inspection of Diesel Engines Subjected to Flooding Conditions-Service Bulletin Number 4021567
  - <https://quickserve.cummins.com/info/index.html>
- Inspection/Repair of Flood Damaged Vehicles with Roadranger Components- TMIB0153
  - [http://www.roadranger.com/ecm/groups/public/@pub/@eaton/@roadranger/documents/content/ct\\_042504.pdf](http://www.roadranger.com/ecm/groups/public/@pub/@eaton/@roadranger/documents/content/ct_042504.pdf)